

## Fire Alarm Mandatory Rejection List

1. A licensed Louisiana fire alarm contractor is not listed on the application.
2. The project is submitted without the professional of record, when one is required.
3. The project is still on hold because of a not-in-compliance architectural review letter.
4. Candela rating of strobes is not identified.
5. Ceiling heights not indicated when ceiling mounted strobes are used.
6. Non-required and non-conforming fire alarm/smoke detection systems with major violations are submitted without a deviation request by the professional of record (where required) or the owner.
7. Whenever emergency forces notification is required by the code and the fire alarm control panel is not listed for this type service. If the panel is listed for this service and they indicate the system is a local system, then cite the requirement for emergency forces notification in lieu of issuing a rejection letter.

## Fire Alarm Discretionary Rejection List

1. Large system battery calculation not provided. Do not reject small systems such as that could be adequately covered by the minimum size battery manufactured.
2. Gross negligence evident in a strobe layout, such as 20 to 25% of required strobes missing from a plan. This office will not design their system.
3. Poor Quality of Drawings:
  - A. Too light to read.
  - B. Room names missing when necessary to determine compliance.
  - C. Cluttered plans.
  - D. Original drawing submitted that is larger than 8 - 1/2" x 14".

HCR/MCM/kmw

5064

fareject